

**SUMMARY FOR WEEK ENDING 1.17.20**

<b>Gradall #40-16</b>	
Eblen Road/Tree Debris	GH Sights/Tree Debris
Greenlick Baptist/Debris	Robards Busby Station/Ditch Work
Martin Martin/Ditch Work	Martin Martin/Shoulder Repairs
Martin Martin/Washout Repairs	
<b>Gradall #41</b>	
Morning Side/Washout Repairs	Walter Road/Pull Shoulders
Walter Road/Ditch Work	Mound Ridge/Washout Repairs
Channey/Ditch Work	
<b>Grader #50</b>	
OOS	
<b>Grader #52</b>	
Green Farm Road	Meahl Cates
Cairo Liles	Smith Denton
Busby Denton	Rock Springs Dixie
Lod Powell Spur	J. Gibson
Sulphur Springs	South WN Royster
Robards Poole	O'Royster
<b>Mower #71</b>	
Kings Mill Road	Martin Martin
Corydon Greenlick Baptist Church	Burbank
<b>Mower #73</b>	
WN Royster	John Steele
Walter Road	
<b>Mower #76</b>	
Sulphur Springs	Pritchett Crooks
Wheeler Road	Lod Powell
John Tapp	
<b>Backhoe #48</b>	<b>Materials Moved</b>
Toy Anthoston/Push Mud From Road	1006.83
Ohio Drive Project	<b>Miscellaneous</b>
	Assist Recycle
<b>Total Patcher #81</b>	Assist Parks
Busby Station Bridge	
Grantwood Hills	
Roberts Busby Station	
Rockhouse	
Corydon Geneva	
Lovers Lane	
Star School	